



PRODUCT DISCONTINUANCE NOTIFICATION PDN #032101

Change Description:

Alliance will be discontinuing all speeds and packages of the AS4LC1M16S1 and AS4LC1M16SO.

Reason for Change:

Alliance Semiconductor has decided to discontinue these products due to market conditions and wafer fabrication constraints.

Key Obsolescence Dates:

Date for last order acceptance: April 30th, 2003

Date for last Alliance shipments: December 31st, 2003


Contact:

Please contact your local Alliance sales representative if you require additional information regarding this discontinuance.

Product Affected:

See above.

Marketing or Sales Signature


5/19/2003

VP of Quality Signature

