



**Alliance Semiconductor Corporation**  
 2575 AUGUSTINE DRIVE, SANTA CLARA, CA.95054  
 TEL.(408) 855-4900 FAX (408) 855-4999

Date: 10/08/04

PCN Tracking Number: PCN ~~014~~4101

AS80M2181A Product Change Notification

**Change Description: Describe highlights/features of product change**

This letter is to serve as a notification of a product change for Alliance Semiconductor part number AS80M2181A.

Description of Change	Part Number Change	
Reason for Change	India Sub Contractor has eliminated bottom marking on production SOIC parts. We had to accommodate these changes by shortening the PN (in order to indicate the PN, D/C. and Lot# on the top of the device).	
Summary of Changes between new and old part	Old (top Marking): AS80M 2181A Lot #	New (top Marking): AS80M218 1 LOT # D/C
	Old (Bottom Marking) D/C	New (Bottom Marking): None
Traceability Guidelines (lot, date code, markings, shipment date)	New parts marked without an "A" at the end of the PN. Lot# C037R	
Update Datasheet/Errata Attached	In Process. Contact Marketing.	
Qual/Test Data Attached	Not Applicable, parts are still the same internally.	
Checked/Included Special Customer's Requirements	N/A	

Part Number (Old)	AS80M2181A
Part Number (New)	AS80M2181
Last Time Buy Date	Not applicable.
Last Time Ship date	Not applicable

Sample availability date	ASAP
PCN effective date	ASAP

Please contact your local sales representative if you have any questions regarding this information.


Sincerely,




VP of Quality  
Anwar Khan



Product Marketing Manager  
Nelson Arata



VP of Sales  
David Casey



Manufacturing Manager  
Cemal Mehmet